

Gas Safe Register Technical Bulletin Index TB 000



Issue number 022

15 October 2010

TB No.	TB 000 Gas Safe Register Technical Bulletin Index - Subject	Publication Date	Status
TB 000	Gas Safe Register Technical Bulletin Index	15.10.10	Current
TB 001	The Gas Industry Unsafe Situations Procedure 6 th edition	01.10.09	Current
TB 002(A)	Reporting of dangerous gas fittings – Reporting of Injuries, Diseases and Dangerous Occurrences Regulations (RIDDOR) as applied to Great Britain	05.08.10	Current
TB 002(B)	Reporting of gas fittings found to be dangerous – Reporting of Injuries, Diseases and Dangerous Occurrences Regulations (RIDDOR) as applied to Northern Ireland	05.08.10	Current*
TB 002(C)	Reporting of dangerous gas fittings – Reporting of Injuries, Diseases and Dangerous Occurrences Legislation (RIDDOR) as applied to the Isle of Man	05.08.10	Current*
TB 002(D)	Reporting of dangerous gas fittings – Reporting an Injury, Disease or Dangerous Occurrence as applied to Guernsey	05.08.10	Current
TB 003	Built-over existing polyethylene (PE) gas services/service pipework – Safety concern	02.09.09	Current
TB 004	Managing risks from inappropriately installed medium pressure-fed domestic sized meter installations located in built-in or surface-mounted boxes	01.04.09	Current
TB 005(A)	Gas cookers in internal kitchens – Ventilation requirements – England and Wales, Isle of Man and Guernsey	15.10.10	Current
TB 005(B)	Gas cookers in internal kitchens – Ventilation requirements – Scotland	15.10.10	Current
TB 005(C)	Gas cookers in internal kitchens – Ventilation requirements – Northern Ireland	19.08.10	Current
TB 006	Industry guidance for the checking of case seals and general integrity of room-sealed fan assisted positive pressure gas appliances	19 .08.10	Current
TB 007	Room-sealed (natural/fanned draught) and open-flued (fanned draught) appliance flues terminating within covered passageways (ginnells)	15.10.10	Current*

* Indicates change since last published

TB No.	TB 000 Gas Safe Register Technical Bulletin Index - Subject (continued)	Publication Date	Status
TB 008	Room-sealed fanned draught flue systems concealed within voids	01.04.09	Current
TB 009	Sealing of extraneous pipe/cable entries to back boiler/circulator enclosures	17.06.10	Current
TB 010	LPG - BS EN 12864 (Annex D) Regulator Blockages	17.06.10	Current
TB 011	The use of clips to secure vapour phase LPG hose and tubing to BS 3212 and EN 1763 to end fittings	17.06.10	Current
TB 012	Visual risk assessment of gas appliances	17.06.10	Current
TB 013	Air/Gas ratio valves	01.04.09	Current
TB 014	Gas Work	19 .08.10	Current
TB 015	The requirement to install gas appliances (including cooking appliances) with flame supervision on all burners in flats and other multi-dwelling buildings	17.06.10	Current
TB 016	Room-sealed flue/chimney terminations – Possible nuisance from fumes and the use of plume management kits	19 .08.10	Current
TB 017	HSE issues safety alert on gas appliance flues in ceiling voids	19 .08.10	Current
TB 018	Glow-worm 'xi' range of boilers – Product modification and servicing reminder	01.09.10	Current
TB 019	British Standard 7967 Carbon monoxide in dwellings and the combustion performance of gas-fired appliances	20.09.10	Current
TB 020	ACS combustion performance assessment (CPA1)	05.08.10	Current
TB 021	Measuring combustion performance to satisfy the requirements of GSIUR 1998 Certificate of Exemption No. 1 of 2008	19 .08.10	Current
TB 022	Installation of previously used domestic gas cooking appliances	19 .08.10	Current
TB 023	Condensing boiler installation assessment procedure – England, Wales Northern Ireland, Isle of Man and Guernsey	17.06.10	Current
TB 024	Condensing Boiler Installation Assessment Procedure (Scotland)	17.06.10	Current
TB 025	Contractor responsibilities when disconnecting and reconnecting gas cooking appliances fitted with a bayonet fitting, or other self-sealing connectors	19 .08.10	Current
TB 026	Effect of fans on open-flued gas appliances – Advice for non-gas operatives	19 .08.10	Current
TB 027	Domestic heating compliance guide & non-domestic heating, cooling and ventilation compliance guides	19 .08.10	Current
TB 028	Electro-osmotic damp-proofing systems	17.06.10	Current
TB 029	Air supply from roof spaces	17.06.10	Current

* Indicates change since last published

TB No.	TB 000 Gas Safe Register Technical Bulletin Index - Subject (continued)	Publication Date	Status
TB 030	Chimney terminations for decorative fuel effect (DFE) gas appliances	17.06.10	Current
TB 031	Gas pipework identification – colour coding	17.06.10	Current
TB 032	Potterton Prima 'C' compartment ventilation	17.06.10	Current
TB 033	Valliant - Pressure loss through appliance gas valves (Withdrawn by Valliant 01.09.10)		Withdrawn
TB 034	Open-flued appliances in bathrooms - a "potted history"	19 .08.10	Current
TB 035	Carrying out gas work on an waterway craft	19 .08.10	Current
TB 036	Fixed hobs and ovens – Flexible gas supplies	17.06.10	Current
TB 037	Cannon Coalridge balanced-flue gas fire - potential safety issue	17.06.10	Current
TB 038	Gas fires and pre-cast chimney/flue systems	17.06.10	Current
TB 039	Warm Air Heaters - The history of return air arrangements for open-flued appliances	01.09.10	Current
TB 040	Meter Box - Installation pipe sleeving	01.07.10	Current
TB 041	BS 5440-2 - Multi-appliance ventilation requirements	01.07.10	Current
TB 042	Repairs following reported gas escapes	01.07.10	Current
TB 043	Electrical work on gas appliances	19 .08.10	Current
TB 044	Flame-failure protection on new and previously used gas catering equipment	09.06.10	Current
TB 045	Re-lighting existing gas appliances after carrying out a tightness test	19 .08.10	Current
TB 046	Gas tightness testing requirements	19 .08.10	Current
TB 047	Pre-cast chimney/flue cooler plates	17.06.10	Current
TB 048	Gas Supply Rights of Entry Regulations 1996	19 .08.10	Current
TB 049	Spillage testing with decorative re-circulatory ceiling fans present	17.06.10	Current
TB 050	Suitability of plasterboard within the builder's opening	17.06.10	Current
TB 051	Ventilation of kitchens in catering establishments	19 .08.10	Current
TB 052	Cleaning high efficiency heat exchangers	01.07.10	Current

* Indicates change since last published

TB No.	TB 000 Gas Safe Register Technical Bulletin Index - Subject (continued)	Publication Date	Status
TB 053	Modular boiler installations	01.07.10	Current
TB 054	Leakage of combustion products from positive pressure fan-assisted boilers	01.07.10	Current
TB 055	Duties of Landlords	19 .08.10	Current
TB 056	Installation of open-flued appliances in domestic garages	19 .08.10	Current
TB 057	Passive stack ventilation	19 .08.10	Current
TB 058	Painted appliance cases	19 .08.10	Current
TB 059	Potential gas escapes on the stainless steel pliable or semi rigid gas meter connections	01.07.10	Current
TB 060	Provision for compartment ventilation (Domestic)	01.07.10	Current
TB 061	Reducing the size of builder's openings and fireplace recesses	17.06.10	Current
TB 062	The 'Benchmark' Scheme	19.07.10	Current
TB 063	Carrying out gas work on leisure accommodation vehicles, residential park homes and holiday accommodation	19 .08.10	Current
TB 064	Gas safety concern - Widney, Nevada and Regency gas fires	19.07.10	Current
TB 065	LPG Cabinet space heaters and the requirements of legislation	19 .08.10	Current
TB 066	Morco Model D-61B, 61E and G111E water heaters	19.07.10	Current
TB 067	Carfield-Geminox Boilers – Inappropriate flue materials	19.07.10	Current
TB 068	Open-flue chimney terminations in proximity to structures	19.07.10	Current
TB 069	HSE Press release regarding replacing ductile iron gas mains	19 .08.10	Current
TB 070	Gas and electric appliances known to contain asbestos containing materials	01.04.09	Current
TB 071	Checking the operating pressure of the meter regulator - Natural gas	19.07.10	Current
TB 072	Separation distances between LPG cylinders and tanks and domestic oil tanks	19.07.10	Current
TB 073	Glow worm Micron case seal modification	01.09.10	Current
TB 074	Use of preformed pipe insulation for protection of gas pipework in concrete floors	19.07.10	Current
TB 075	Glow-worm Micron boiler range – Product recall (Withdrawn by Glow-worm 01.09.10)		Withdrawn

* Indicates change since last published

TB No.	TB 000 Gas Safe Register Technical Bulletin Index - Subject (continued)	Publication Date	Status
TB 076	Electronic records and signatures	19.08.10	Current
TB 077	Product recall notice – Installer notification – Buderus 500 and 600 domestic boiler series	19.08.10	Current
TB 078	Vaillant ecoMAX and ecoTEC ranges of boilers – product modification and servicing reminder	01.09.10	Current
TB 079	BS 5482-1:2005 LPG Installations – Additional Guidance	19.08.10	Current
TB 080	Changes to LPG regulator Standards	19.08.10	Current
TB 081	Electricity at Work Regulations 1989 (Statutory Instrument No 1988/635)	19.08.10	Current
TB 082	Discharging condensate into cast-iron waste systems	19.08.10	Current
TB 083	Domestic Bulk Liquefied Petroleum Gas Market Investigation Order - 2008	19.08.10	Current
TB 084	The prohibition of two pliable connectors on a domestic gas meter installation	22.09.09	Current
TB 085	BEKO gas cooker product range modification	20.09.10	Current
TB 086	GDHA gas cooker product range modification	20.09.10	Current
TB 087	Warm air heaters - change to spillage testing requirements	01.09.10	Current
TB 088	Flueless Gas Fires – the importance of correct installation and commissioning	01.09.10	Current
TB 089	Requesting a gas supply to a domestic property	15.10.10	Current*
TB 090	Loctite 55 pipe sealing cord – suitability for use on gas work	01.09.10	Current
TB 091	Decommissioning part of a combined appliance	01.09.10	Current
TB 092	Domestic ducted warm air heaters and systems – gas safety checks	01.09.10	Current
TB 093	An overview of the revised Catering Information Sheet 23 <i>Gas safety in catering and hospitality</i>	20.09.10	Current
TB 094	Tightness testing of an existing domestic natural gas MP-fed installation without an MIV	01.09.10	Current
TB 095	Effect of mechanical fans on open-flued appliances	17.06.10	Current
TB 096	Confirmation of FSD functionality for central heating boilers, water heaters and ducted warm air heaters	01.09.10	Current
TB 097	Possible damage to backplate strapped fittings and gas escapes from self-sealing connectors (cooker bayonets)	01.09.10	Current
TB 098	Vaillant ecoTEC range of boilers – product modification	01.09.10	Current

* Indicates change since last published

TB No.	TB 000 Gas Safe Register Technical Bulletin Index - Subject (continued)	Publication Date	Status
TB 099	Glow-worm Micron range of boilers – Important safety notice (Withdrawn by Glow-worm 01.09.10)		Withdrawn
TB 100	Dealing with damaged pre-fabricated built-in domestic gas meter boxes	01.09.10	Current
TB 101	HSE Safety Alert – Risks from redundant solid fuel back boilers	01.09.10	Current
TB 102	Location of protective equipotential bonding on gas installation pipework in domestic premises	01.09.10	Current
TB 103	The application of the BS 7967 suite of Standards – The investigation of a report of fumes, smells, spillage/leakage of combustion products, or CO detector activation	20.09.10	Current
TB 104	The installation of thermoplastic CWSC and the safety of immersion heaters	01.09.10	Current
TB 105	Non room-sealed appliances located in sleeping accommodation	01.09.10	Current
TB 106	Corrosion protection of gas installation pipework using grease impregnated tape	20.09.10	Current
TB 107	Glow-worm updated combustion tolerances (Withdrawn by Glow-worm 01.09.10)		Withdrawn
TB 108	Ideal Boilers – Information Bulletin	20.09.10	Current
TB 109	European Directive for the Energy Performance of Buildings – Article 8 – providing energy efficiency advice on heating and hot water systems	20.09.10	Current
TB 110	Tightness testing domestic sized natural gas installations with G10/U16, G4/U6 and E6 gas meters	20.09.10	Current
TB 111	The use of anaerobic compound as a bonding agent to join copper pipework to copper capillary fittings conveying gas	20.09.10	Current
TB 112	Obtaining a meter index reading on a Landis + Gyr Libra 210 meter	20.09.10	Current
TB 113	Research into available ventilation in modern floor voids	20.09.10	Current
TB 114	Responding to a request to attend to flood damaged gas appliances and pipework	20.09.10	Current
TB 115	Worcester condensing boilers – Inlet gas pressures – Amendment to installation instructions	20.09.10	Current
TB 116	Always use the appliance manufacturer's specified spare parts when replacing gas controls	20.09.10	Current
TB 117	The dangers of cables buried in walls and partitions	20.09.10	Current
TB 118	Safe electrical isolation of gas appliances	20.09.10	Current
TB 119	Electrical safety requirements for gas appliances installed in rooms or spaces containing baths or showers	20.09.10	Current
TB 120	The use of corrugated stainless steel semi-rigid gas piping in domestic and non-domestic installations	20.09.10	Current

* Indicates change since last published

TB No.	TB 000 Gas Safe Register Technical Bulletin Index - Subject (continued)	Publication Date	Status
TB 121	Contractor responsibilities when disconnecting and reconnecting gas cooking appliances fitted with a bayonet fitting, or other self-sealing connectors		Withdrawn See TB 025
TB 122	Approved Document P – Electrical Safety – Dwellings	20.09.10	Current
TB 123	Replacement room-sealed appliances for SE Duct and U Duct chimney systems	20.09.10	Current
TB 124	LPG on boats, yachts & other vessels - Update on gas tightness testing, system pressure gauges and regulators	20.09.10	Current
TB 125	Health and safety guidance to be made available for no cost online	20.09.10	Current
TB 126	Combustion performance information for condensing boilers incorporating air/gas ratio control valve technology	06.11.09	Current
TB 127	Gas industry guidance on work on meter installations	19.07.10	Current
TB 128	Halstead CB, SB and VB range of boilers – Product modification and servicing reminder	01.10.10	Current
TB 999	Gas Safe Register Normative Document List	01.10.10	Current
TB 1000	Introduction to Gas Safe Register Technical Bulletins	09.06.10	Current

* Indicates change since last published

-o0o-